## Zyklop Mini

## For confined spaces

## **Tool-Check PLUS**



28 bits, 1 hand holder 813 suitable for the attachment of bits with  $^{1}\!\!/_4$ " hexagon drive as per DIN ISO 1173-C 6,3 and Wera connection series 1, 1 Rapidaptor bit holder, 1 adaptor 870/1 ( $^{1}\!\!/_4$ " hexagon to  $^{1}\!\!/_4$ " square), 7 sockets ( $^{1}\!\!/_4$ "); 1 Wera Bit Ratchet, drop-forged full steel design suitable for the attachment of bits with  $^{1}\!\!/_4$ " hexagon drive as per DIN ISO 1173-C 6,3 and E 6,3 and Wera connection series 1 and 4; the use of  $^{1}\!\!/_4$ " sockets is also possible with the application of the Wera adaptor 870/1

05 <b>056490</b> 001		
	8001 A	1 x 1/4"x87,0
•	813	1 x 1/4"x78
●0	889/4/1 K	1 x 1/4"x50
00	870/1	1 x 1/4"x25
•	8790 HMA	1 x 5,5x23,0; 1 x 6,0x23,0; 1 x 7,0x23,0;
		1 x 8,0x23,0; 1 x 10,0x23,0; 1 x 12,0x23,0;
		1 x 13,0x23,0
0	851/1 TZ PH	2 x PH 1x25; 3 x PH 2x25; 1 x PH 3x25
0	855/1 TH PZ	1 x PZ 1x25; 3 x PZ 2x25; 1 x PZ 3x25
0	867/1 TZ	1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25;
	TORX®	1 x TX 25x25; 1 x TX 30x25; 1 x TX 40x25
0	867/1 Z TORX <sup>©</sup>	P1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25;
	B0	1 x TX 25x25; 1 x TX 30x25
0	840/1 Z	1 x 3,0x25; 1 x 4,0x25; 1 x 5,0x25; 1 x 6,0x25;
	Hex-Plus	1 x 8,0x25
•	800/1 TZ	1 x 1,0x5,5x25



77 To learn more about this product, scan the QR code. 66

## **Tool-Check PLUS Imperial**







28 bits, 1 hand holder 813 suitable for the attachment of bits with  $^{1}\!\!I_{4}^{"}$  hexagon drive as per DIN ISO 1173-C 6,3 and Wera connection series 1, 1 Rapidaptor bit holder, 1 adaptor 870/1  $(^{1}\!\!I_{4}^{"})$  hexagon to  $^{1}\!\!I_{4}^{"}$  square), 7 sockets  $(^{1}\!\!I_{4}^{"})$ ; 1 Wera Bit Ratchet, drop-forged full steel design suitable for the attachment of bits with  $^{1}\!\!I_{4}^{"}$  hexagon drive as per DIN ISO 1173-C 6,3 and E 6,3 and Wera connection series 1 and 4; the use of  $^{1}\!\!I_{4}^{"}$  sockets is also possible with the application of the Wera adaptor 870/1

05 <b>056491</b> 001		
	8001 A	1 x 1/4"x87,0
•	813	1 x 1/4"x78
●0	889/4/1 K	1 x 1/4"x50
00	870/1	1 x 1/4"x25
•	8790 HMA	1 x 3/16"x23,0; 1 x 1/4"x23,0; 1 x 5/16"x23,0;
		1 x 11/32"x23,0; 1 x 3/8"x23,0;
		1 x 7/16"x23,0; 1 x 1/2"x23,0
•	851/1 TZ PH	2 x PH 1x25; 3 x PH 2x25; 1 x PH 3x25
	800/1 TZ	1 x 1,0x5,5x25
0	867/1 TZ	1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25;
	TORX®	1 x TX 25x25; 1 x TX 30x25; 1 x TX 40x25
•	867/1 Z TORX <sup>©</sup>	<sup>9</sup> 1 x TX 10x25; 1 x TX 15x25; 1 x TX 20x25;
	B0	1 x TX 25x25; 1 x TX 30x25
0	840/1 Z	1 x 3/32"x25; 1 x 1/8"x25; 1 x 5/32"x25;
	Hex-Plus	1 x 3/16"x25; 1 x 5/16"x25
0	868/1 V	1 x # 1x25; 3 x # 2x25; 1 x # 3x25